

## **GOL SAFETY VIOLATIONS**

**Drop starting a chainsaw**

**Starting a chainsaw without the chain brake engaged**

**Taking more than 2 steps without the chain brake engaged**

**Taking a hand off the chainsaw without the chain brake engaged**

**Running your saw above an idle without hearing protection**

**Cutting anything without your face screen down or safety glasses on**

**Hitting a wedge without your face screen down or safety glasses on**

**Starting a bore cut with the kickback corner**

**Boring more than halfway through a tree from the bad side**

**Not escaping from the tree a minimum of 15 feet at 45 degree angle**

**Not having both thumbs wrapped around the handles**